



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D350-607-541
Job Sheet 182731



005650

Part No: D350-607-541

Job Qty: 1 ea

Part Name: AS350/AS355 Quick Release Heli-Utility-Basket™ Long, Heavy Duty Lid



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 8/30/18

Job Tracking No:

Due Date: 10/5/18

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: IIN-D350-607 REV E SHEET 22 IPP REV:A 10-08-19 AS PER REV.A DD VERF BY:EC IPP Rev:B 11.02.09 add to install label DD verf by:EC IPP REV:C 12.03.06 AS PER ECN12-535 DD VERF:EC IPP REV:D 12.07.24 AS PER ECN 12-610 DD VERF:EC IPP REV:E 13.08.21 CHG005 / ECN 13-624 DD VERF:JLM IPP REV:F 14.06.09 AS PER ECN14-572 DD VERF:JLM IPP REV:G 16.09.12 added note at seq120 PAR16-515 DD VERF:JLM IPP Rev.H 17.06.08 As Per IIN Rev.E DP Verify DD

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	10/5/18	10/5/18	0.00	0.00	Start Up Stores/Pkg-2		SEP 25 2018
110	Packaging	1 pcs	10/5/18	10/5/18	0.00	0.00	Packaging1-3		DAS 8-89
120	QC	1 pcs	10/5/18	10/5/18	0.00	0.00	QC4		DAS 6-69
130	Packaging	1 pcs	10/5/18	10/5/18	0.00	0.00	Packaging3-1		DAS 6-9-89
135	DC	1 pcs	10/5/18	10/5/18	0.00	0.00	DC		DAS 9-89
140	QC21-FG	1 Ea	10/5/18	10/5/18	0.00	0.00	QC21		OCT 05 2018

Part Op 130 - Package as per PPPD350-607-541

Descriptions: 135 - Photocopy bluefile & type labels per PPP D350-607-541 CHG008

DAS
21
9-89

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
AN310C4	Nut	1 Ea (1 ea)	90-Start up Operation	5065268
AN4-13A	Bolt	6 Ea (6 ea)	90-Start up Operation	5089302
AN4C15	BOLT	1 Ea (1 ea)	90-Start up Operation	5053946
D2690-6	Lanyard	1 Ea (1 ea)	90-Start up Operation	5094895
D3912-041	Eyebolt Receiver Assembly	1 Ea (1 ea)	90-Start up Operation	5104876
D4086-200	Placard, Max Load	1 Ea (1 ea)	90-Start up Operation	5090640
D4150-041	Attachment Arm Assembly	1 Ea (1 ea)	90-Start up Operation	5091366
D4151-041	Basket Fwd Hardpoint Assembly, Lower	1 Ea (1 ea)	90-Start up Operation	5104907
D4151-043	Basket Fwd Hardpoint Assembly, Upper	1 Ea (1 ea)	90-Start up Operation	5104918
D4917-300	Placard, Max Load	1 Ea (1 ea)	90-Start up Operation	8090951
MS17984-C413	Quick Release Pin	1 pcs (1 ea)		5095270

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____ Date : _____ _____ _____	DISPOSITION Rework ☐ Scrap ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Cross tube ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging Supplier ☐ Engineering Quality ☐ Other ☐ DART AEROSPACE Container No: S113556 Part: D350-607-541 Job No: 182731 Serial No/Batch: S113556 Revision: E Inspector: _____ Exp Date: _____ Instructions: TC STC SH94-14 Issue 7a FFA-STC SR00213NY 15/09/09, EASA S. DART AEROSPACE Ltd. 1270 Aberdeen Street Hawthorn, VIC 3122 Australia Tel: 613 632-6200 Email: sales@dartaero.com www.dartaero.com																																																																																	
		MRB (QSI042) Approval																																																																																	
		Completed By																																																																																	
		Lead hand / Supervisor Approval Verification																																																																																	
		QC / QA Coordinator Approval																																																																																	
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td colspan="2" style="text-align: center;">Root Cause</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Environment</td> <td>☐</td> <td>Offset/Setup</td> <td>☐</td> <td>Centre Not Concentric</td> <td>☐</td> </tr> <tr> <td>Design</td> <td>☐</td> <td>Supplier</td> <td>☐</td> <td>Cracks</td> <td>☐</td> </tr> <tr> <td>Doc/Data</td> <td>☐</td> <td>Training</td> <td>☐</td> <td>Crimp/Kink/Ripple/Wave</td> <td>☐</td> </tr> <tr> <td>Equip/Tooling</td> <td>☐</td> <td>Use for Testing</td> <td>☐</td> <td>Cuffs</td> <td>☐</td> </tr> <tr> <td>Handling/Pre</td> <td>☐</td> <td>Poor Information</td> <td>☐</td> <td>Crushing</td> <td>☐</td> </tr> <tr> <td>Material</td> <td>☐</td> <td>Rushing</td> <td>☐</td> <td>Heat Treat</td> <td>☐</td> </tr> <tr> <td>Internal Transport</td> <td>☐</td> <td>Product Improvement</td> <td>☐</td> <td>Wave/Twist in Tube</td> <td>☐</td> </tr> <tr> <td>Tribal Knowledge</td> <td>☐</td> <td>Process Improvement</td> <td>☐</td> <td>Marks/Chatter</td> <td>☐</td> </tr> <tr> <td>LOA</td> <td>☐</td> <td>Manufacturing Process</td> <td>☐</td> <td></td> <td></td> </tr> <tr> <td>Substation</td> <td>☐</td> <td>Past Due</td> <td>☐</td> <td colspan="2" style="text-align: center;">OTHER : _____</td> </tr> <tr> <td>Past Expiry Date</td> <td>☐</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Misidentified</td> <td>☐</td> <td></td> <td></td> <td></td> <td></td> </tr> </table>						Root Cause						Environment	☐	Offset/Setup	☐	Centre Not Concentric	☐	Design	☐	Supplier	☐	Cracks	☐	Doc/Data	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Equip/Tooling	☐	Use for Testing	☐	Cuffs	☐	Handling/Pre	☐	Poor Information	☐	Crushing	☐	Material	☐	Rushing	☐	Heat Treat	☐	Internal Transport	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Tribal Knowledge	☐	Process Improvement	☐	Marks/Chatter	☐	LOA	☐	Manufacturing Process	☐			Substation	☐	Past Due	☐	OTHER : _____		Past Expiry Date	☐					Misidentified	☐				
Root Cause																																																																																			
Environment	☐	Offset/Setup	☐	Centre Not Concentric	☐																																																																														
Design	☐	Supplier	☐	Cracks	☐																																																																														
Doc/Data	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐																																																																														
Equip/Tooling	☐	Use for Testing	☐	Cuffs	☐																																																																														
Handling/Pre	☐	Poor Information	☐	Crushing	☐																																																																														
Material	☐	Rushing	☐	Heat Treat	☐																																																																														
Internal Transport	☐	Product Improvement	☐	Wave/Twist in Tube	☐																																																																														
Tribal Knowledge	☐	Process Improvement	☐	Marks/Chatter	☐																																																																														
LOA	☐	Manufacturing Process	☐																																																																																
Substation	☐	Past Due	☐	OTHER : _____																																																																															
Past Expiry Date	☐																																																																																		
Misidentified	☐																																																																																		

MS21042L4	Nut	6 Ea (6 ea)	90-Start up Operation	
MS24665-151	Cotter Pin	1 Ea (1 ea)	90-Start up Operation	5094597
NAS1149C0463R	Washer	3 Ea (3 ea)	90-Start up Operation	5053951
NAS1149F0432P	Washer	12 Ea (12 ea)	90-Start up Operation	5053953
NAS1515H4L	Washer	2 Ea (2 ea)	90-Start up Operation	5082558
D4085-3	Placard	1 Ea (1 ea)	90-Start up Operation	5044189
D350-607-511	AS350/AS355 Quick Release Basket/Long Cargo Tube Mounting Provisions, Fits LH/RH	1 Ea (1 ea)	110-Packaging	5105453
D4030-041	Long Basket Assembly (350)	1 Ea (1 ea)	110-Packaging	5116017
				5115723

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	AN310C4	1	154	0
	AN4-13A	6	1,399	0
	AN4C15	1	24	0
	D2690-6	1	35	0
	D3912-041	1	11	0
	D4085-3	1	28	0
	D4086-200	1	8	0
	D4150-041	1	12	0
	D4151-041	1	11	0
	D4151-043	1	8	0
	D4917-300	1	16	0
	MS17984-C413	1	36	0
	MS21042L4	6	5,160	0
	MS24665-151	1	269	0
	NAS1149C0463R	3	348	0
	NAS1149F0432P	12	1,781	0
	NAS1515H4L	2	273	0
110-Packaging	D350-607-511	1	4	0
	D4030-041	1	2	0

Part Specifications

Specifications could not be found.

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

5.0 PARTS LIST

QTY -541	QTY -543	QTY -545	QTY -547	QTY -511	QTY -501	PART NUMBER	DESCRIPTION
X						D350-607-541	HELI-UTILITY-BASKET
	X					D350-607-543	HELI-UTILITY-BASKET
		X				D350-607-545	HELI-UTILITY-BASKET
			X			D350-607-547	HELI-UTILITY-BASKET
1	1	1	1	X		D350-607-511	QUICK RELEASE BASKET MOUNTING KIT
					X	D350-607-501	CONVERSION KIT
1	1	1	1		1	D2690-6	LANYARD
				8	8	D3501-1	BUSHING
				2	2	D3910-3	X-TUBE LUG
				1	1	D3910-5	X-TUBE LUG
				1	1	D3910-7	X-TUBE LUG
1	1	1	1		1	D3912-041	EYEBOLT RECEIVER ASSY
				8	8	D3984-030	RUBBER EXTRUSION, X-TUBE
1						D4030-041	LONG BASKET ASSY
	1					D4030-043	LONG BASKET ASSY, LIGHTWEIGHT
		1				D4032-041	SHORT BASKET ASSY
			1			D4032-043	SHORT BASKET ASSY, LIGHTWEIGHT
1					1	D4917-300	PLACARD, MAX LOAD
1						D4086-200	PLACARD, MAX LOAD
	1				1	D4917-315	PLACARD, MAX LOAD
	1					D4086-215	PLACARD, MAX LOAD
		1			1	D4917-320	PLACARD, MAX LOAD
		1				D4086-220	PLACARD, MAX LOAD
			1		1	D4917-332	PLACARD, MAX LOAD
1	1	1	1	1	1	D4085-3	PLACARD, INSTRUCTIONS
			1			D4086-232	PLACARD, MAX LOAD
				1	1	D4148-041	FWD X-TUBE LUG ASSY
				1	1	D4149-041	AFT X-TUBE LUG ASSY
1	1	1	1		1	D4150-041	ATTACHMENT ARM ASSY
1	1	1	1		1	D4151-041	BASKET FWD HARDPOINT ASSY (LOWER)
1	1	1	1		1	D4151-043	BASKET FWD HARDPOINT ASSY (UPPER)
				1	1	D4713-1	SPACER
				2	2	D4775-041	STRUT ASSEMBLY
				2	2	D4776-3	SKIDTUBE CLEVIS
6	6	6	6		6	AN4-13A	BOLT
				20	22	AN4-14A	BOLT
				4	4	AN4-42A	BOLT
1	1	1	1		1	AN4C15	BOLT
1	1	1	1		1	AN310C4	CASTELLATED NUT
				2	2	AN6-13A	BOLT
1	1	1	1		1	MS17984-C413	QUICK RELEASE PIN
6	6	6	6	24	32	MS21042L4	NUT (OR MS21042-4)
				2	2	MS21042L6	NUT
1	1	1	1		1	MS24665-151	COTTER PIN
				1	1	MS3367-5-0	TIE WRAP
2	2	2	2		2	NAS1515H4L	WASHER
12	12	12	12	40	56	NAS1149F0432P	WASHER
3	3	3	3		3	NAS1149C0463R	WASHER
				4	4	NAS1149F0663P	WASHER

• COPYRIGHT © 2010 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

REFERENCE ONLY

Revision: E

Date: 16.11.25

PAGE 1 OF 1

Description: HELI-UTILITY BASKET

H:\Forms\Engineer\Approved Eng Online\CHGREC revB